




OUTFIT RH 2. GENERAL WIRING DIAGRAM.





TO GYRO
SUPPLY



TO 220V.
D.C. SUPPLY.

PATT. 5342 FUSE,
CARTRIDGE TYPE B,
3 AMP.



PATT. 9084



PATT. 4880
JUNCTION BOX.

230V.
50 \sim
A.C. SUPPLY